

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

WEST UNION BRIDGE  
Spanning Sugar Creek, CR 525W  
West Union  
Parke County  
Indiana

HAER IN-105

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, May 2004

IN-105-1	GENERAL VIEW FROM NORTHWEST.
IN-105-2	GENERAL VIEW FROM SOUTH.
IN-105-3	VIEW OF SOUTH PORTAL, FROM SOUTH.
IN-105-4	ELEVATION OF SOUTH PORTAL WITH SCALE.
IN-105-5	ELEVATION OF SOUTH PORTAL WITHOUT SCALE.
IN-105-6	OBLIQUE VIEW OF SOUTH CONCRETE APPROACH WALL, BUILT IN 1914 AFTER A FLOOD DAMAGED ORIGINAL WALLS.
IN-105-7	ELEVATION OF WALL INSCRIPTION, SHOWING 1914 DATE AND NAMES OF COUNTY OFFICIALS AT TIME.
IN-105-8	ELEVATION OF SOUTH ABUTMENT FROM NORTH WITH SCALE.
IN-105-9	ELEVATION OF SOUTH ABUTMENT FROM NORTH WITHOUT SCALE.

WEST UNION BRIDGE  
HAER IN-105  
INDEX TO PHOTOGRAPHS

IN-105-10	DETAIL OF SOUTHEAST CORNER OF ABUTMENT WITH SCALE. NOTE STAY ROD EXTENDING FROM BOTTOM CHORD AND ANCHORED INTO ABUTMENT WITH IRON EYEHOOK. THIS FEATURE SECURED THE SUPERSTRUCTURE OF THE BRIDGE TO THE ABUTMENTS TO PREVENT THE TRUSS FROM BEING WASHED DOWNSTREAM IN FLOODS. NOTE ALSO THE CAST IRON PLATE ON WHICH THE ARCH BEARS, WHICH WAS DESIGNED TO PROLONG THE LIFE OF THE ARCH ENDS, ONE OF THE MOST VULNERABLE SPOTS ON A TIMBER BRIDGE.
IN-105-11	DETAIL OF SOUTHEAST CORNER OF ABUTMENT WITHOUT SCALE.
IN-105-12	VIEW OF CENTER OF ABUTMENT FROM SOUTH.
IN-105-13	VIEW OF INTERIOR FROM NORTH.
IN-105-14	VIEW FROM EAST WINDOW LOOKING EAST.
IN-105-15	OBLIQUE VIEW OF INTERIOR ARCH.